

A.D.A. INSPECTION REPORT

FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

TABLE OF CONTENTS

ANNIE BECK PARK	PAGE 1
BASS PARK	PAGE 2
BAYVIEW PARK	PAGE 3
BEACH	PAGE 4
BENESON PARK	PAGE 5
BENNETT PARK	PAGE 6
BUBIER PARK & EXTENSION (WEST OF BRIDGE)	PAGE 7
CLIFF LAKE	PAGE 8
COOLIE HAMMOCK	PAGE 9
CORAL RIDGE PARK	PAGE 10
CROISSANT PARK & POOL	PAGE 11
DILLARD	PAGE 12
ESPLANADE PARK	PAGE 13
FLAMINGO PARK	PAGE 14
FLORANADA PARK	PAGE 15
FLORENCE HARDY PARK	PAGE 16
FLOYD HULL STADIUM	PAGE 17 - 18
FORT LAUDERDALE CONSERVATION CORP TRAINING	PAGE 19
FORT LAUDERDALE HIGH-TENNIS & POOL	PAGE 20
GEORGE ENGLISH PARK	PAGE 21 - 22
GREEN FIELD	PAGE 23
GUTHRIE BLAKE	PAGE 24
HARBORDALE	PAGE 25
HECTOR PARK	PAGE 26
HOLIDAY PARK	PAGE 27 - 28
HOLIDAY PARK ACTIVITY CENTER	PAGE 29
HOLIDAY PARK COMMUNITY CENTER	PAGE 30
HOLIDAY PARK GYM	PAGE 31
HOLIDAY PARK SOCIAL CENTER	PAGE 32
HOLIDAY PARK SPECIAL EVENTS BUILDING	PAGE 33
HORTT	PAGE 34
IMPERIAL POINT	PAGE 35
J. J. VERA'S PARK	PAGE 36
LANDINGS	PAGE 37
LAUDERDALE MANORS PARK	PAGE 38 - 39
LAUDERDALE PARK	PAGE 40
LAUDERDALE VILLAS ENTRANCE	PAGE 41
LINCOLN PARK	PAGE 42
MAJ. WILLIAM LAUDERDALE PARK	PAGE 43
MERLE FOGG/IDLEWYLD	PAGE 44
MILLS POND PARK	PAGE 45 - 46
MORTON ACTIVITY CENTER	PAGE 47
NORTHFORK	PAGE 48
PARKS & RECREATION ADMINISTRATION OFFICE	PAGE 49
POINCIANA PARK	PAGE 50
PROVIDENT PARK	PAGE 51

TABLE OF CONTENTS

RIO VISTA PARK	PAGE 52
RIVERSIDE PARK	PAGE 53
RIVERWALK	PAGE 54
ROGERS FIELD	PAGE 55
SISTRUNK EAST ENTRY	PAGE 56
SNYDER PARK	PAGE 57 - 58
SOUTH BEACH PARK	PAGE 59
STRANAHAN - POOL	PAGE 60
STRANAHAN PARK	PAGE 61
SUNLAND GYM	PAGE 62
SUNLAND PARK	PAGE 63
SUNLAND POOL	PAGE 64
SUNLAND RECREATION CENTER	PAGE 65
SUNLAND SOCIAL CENTER	PAGE 66
SUNSET	PAGE 67
SWEETING PARK	PAGE 68
SWIMMING HALL OF FAME	PAGE 69 - 71
TARPON COVE	PAGE 72
TARPON RIVER PARK	PAGE 73
TENNIS CENTER	PAGE 74
TOWNSEND PARK	PAGE 75
VICTORIA PARK	PAGE 76
VIRGINIA YOUNG PARK	PAGE 77
VISTA PARK	PAGE 78
WALKER PARK	PAGE 79
WAR MEMORIAL AUDITORIUM	PAGE 80
WARFIELD PARK	PAGE 81
WESTWOOD HEIGHTS	PAGE 82
WESTWOOD TRIANGLE	PAGE 83
WILLINGHAM	PAGE 84
YANKEE STADIUM	PAGE 85 - 86

1.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: ANNIE BECK PARK

LOCATION: Victoria Park & Northeast First Street

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space with no accessibility.

Old deck is unsafe for everyone.

Two sets of old stairs should be removed.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: BASS PARK

LOCATION: 2750 Northwest 19 Street

DATE OF INSPECTION: January 14, 1993

INSPECTOR(S): Susan Retz, Jim Kern, Bob Stried, Mike Fay, Suzanne Broucek

FACILITY CONTACT/PHONE: David Deal - 739-8498

A.D.A. CONCERNS: No designated disabled parking on east end by tennis courts.

No access to basketball courts.

Playground is accessible by sidewalk. None of the play equipment is accessible and is surrounded by sand.

Pool area is accessible through rec center, but it is in need of proper signage. There is no lift for access to water.

Pool showers and water fountain are not accessible.

Shaded bleacher area does not provide wheelchair space.

Community Center

Restrooms will meet requirements with some minor adjustments. Grab bars need to be extended. Soap dispensers should be lowered.

Kitchen counter is too high, must provide alternative service.

Air conditioning controls are too high (62").

No access from the back of the building because of step.

This facility has limited parking, and the committee felt the one designated disabled space may be too remote for building.

3.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION

FACILITY: BAYVIEW PARK

LOCATION: 4400 Bayview Drive

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Twenty-seven (27) parking spaces are offered. Two spaces need to be designated disabled and lined properly.

A sidewalk around the park's circumference would provide access to most of the amenities.

Basketball courts have no access.

Ramp to tennis courts needs a landing area. Gate latch is too high.

Signage is too high and flat.

Telephone is too high and needs a flat landing.

Restrooms are not accessible (step up) and do not meet any requirements.

Concession stand is not accessible (steps) and counter is too high.

Field #1: If fence was removed from dugout end, they would be accessible.

No covered seating is provided for wheelchair.

Water fountain is not accessible.

Playground is not accessible.

Playground equipment does not meet requirements and is surrounded by sand.

T-Ball Field bleachers need to be uprighted. They have no access.

Pony League Field has no access to field or bleachers.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: BEACH

LOCATION: Sunrise Boulevard to NE 18 Street

DATE OF INSPECTION: March 4, 1993

INSPECTOR(S): Larry Ewald, Mike Fay, Jim Kern, Bob Stried,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS:

Sunrise Blvd. to N.E. 18 Street

This area has just been resurfaced. There are presently two disabled parking spaces with signs and no lining. Spaces required would depend on number of spaces.

No access to any of the showers.

No access to any of the cabanas.

South Beach Park to Sunrise Blvd.

Lifeguard tower signage does not meet requirements for visually impaired.

All entrances to the beach are steps which makes it inaccessible.

Showers are also located on steps and are inaccessible. Handles are too high and are grip models.

Garbage cans along north end of beach are in the sand and are not accessible from sidewalk.

There is a disabled beach area at Sebastian Street and A1A. A flat surface and shorter shower are available. Signage needs to be blue. This area needs to have access to the water provided. This may be done with a ramp or beach wheelchairs.

There is a lifeguard station at this entrance.

Parking for this area is under construction west of A1A. It looks like space for five - six vehicles, with ramps and curb cuts available for passage across A1A to beach. Ramp should have handrails.

This area, when completed, may meet A.D.A. requirements for entire beach access. However, there are no restrooms for anyone at this location.

Vistamar Street & A1A disabled parking needs to be relined to meet requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: BENENSON PARK

LOCATION: Southwest 14 Street & 33 Terrace

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking for anyone.

Playground has no accessible play equipment. It is also surrounded by sand. No access to bench near playground.

Water fountain is not accessible.

This park does have excellent access to basketball courts, tennis courts and to the sand area of the playground. Its design could be used for future parks to meet A.D.A. requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: BENNETT PARK

LOCATION: 1755 Northeast 14 Street

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Bob Stried, Larry Ewald,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park has been taken over by portable classrooms for Bennett Elementary School.

No disabled parking is available.

Playground has limited equipment left and does not meet requirements.

No access to basketball courts.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: BUBIER PARK & EXTENSION (WEST OF BRIDGE)

LOCATION: South Andrews Avenue and New River Drive

DATE OF INSPECTION: March 16, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Jim Kern, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Under construction.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: CLIFF LAKE

LOCATION: Southeast 12 Way & 14 Street

DATE OF INSPECTION: March 3, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space along Cliff Lake.
There is no parking or services available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: COOLEE HAMMOCK

LOCATION: Southeast 15 Avenue & Brickel Drive

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Mike Fay, Jim Kern, Larry Ewald, Bob Stried,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Parking area is rough and needs paving. One designated disabled parking space is needed.

No access is available to benches in river area. A sidewalk is needed.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: CORAL RIDGE PARK

LOCATION: Bayview Drive & Northeast 12 Avenue

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking for anyone.

This park offers open green space with sidewalk and an old fountain in the middle of park.

Sidewalk has cracks. Fountain and brick bench walls are also cracked and crumbling.

Metal covers around fountain are missing, leaving holes in the walk way (safety problems).

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: CROISSANT PARK & POOL

LOCATION: Southwest 17 Street & 4th Avenue

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Entrance ramp to pool is too steep.

Pool restrooms, water fountains and showers do not meet any requirements.

There is no designated parking for anyone.

Restroom pavilion behind pool does not meet requirements and has no direct access. This pavilion is scheduled for demolition. The School Board appears to be building a new restroom facility.

Both baseball fields have no access to fields, bleachers, etc.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: DILLARD

LOCATION: 2501 Northwest 11 Street

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: The basketball courts and softball fields have been taken over by the construction crews and the expansion of Dillard High School.

No facilities exist at this time for anyone.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: ESPLANADE PARK

LOCATION: Southwest Second Street

DATE OF INSPECTION: March 16, 1993

INSPECTOR(S): Jim Kern, Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking for anyone. City Parking Garage is available across the street.

Handrails on ramps to the gazebo need to be extended.

Water fountains are too high.

Door on ladies restroom needs pressure adjusted. Signage is needed for disabled restroom.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: FLAMINGO PARK

LOCATION: 1900 Southwest 21 Avenue

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking is available at this park. There is room for parking along Southwest 21 Way that is not paved.

There is no access to the park, sidewalks are needed.

Playground has no accessible equipment.

It is also surrounded by sand.

Exercise stations are not accessible and are surrounded by sand.

Exercise signs do not meet requirements for visually impaired.

Three (3) benches and two (2) trash cans are not accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: FLORANADA PARK

LOCATION: 5251 Northeast 14 Way

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Parking lot has 25 spaces with no designated disabled spaces. One is needed.

Concession stand window is too high.

End fence on dugout would need to be removed for access.

Pay phone is too high and has no landing or access.

Water fountain does not meet requirements and is inaccessible.

Restrooms have a lip on door and do not meet any requirements.

Sidewalk on east entrance to restrooms is good. It should be extended around the park for complete accessibility.

Exercise path is in poor shape (muddy), signage is not accessible for visually impaired.

Playground is not accessible, surrounded by sand. There is one accessible piece of play apparatus.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: FLORENCE HARDY PARK

LOCATION: 25 Southwest 9 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Ninth Street parking lot has forty spaces with one disabled space. This lot needs to be relined and have another disabled space added.

There is no accessibility to softball field or bleacher area.

Restrooms now belong to the county and are scheduled for demolition.

Seventh Street parking lot has eleven spaces with no disabled spaces. One is needed.

Pathway to building and courts needs to be widened and resurfaced. Ramp to sidewalk and building too narrow and steep.

Building has no access because of step.

Inside restrooms are very old and do not meet requirements.

Outside restrooms are not accessible due to lip at entrances. They are also not large enough to meet requirements.

Sidewalk along Seventh Street has no curb cuts into park.

Sidewalk to tennis courts has been pulled up by tree roots and needs to be fixed to make it level.

Tennis court entrances are in need of more asphalt to fill in holes to make it level and accessible.

Lawn bowling green has no wheelchair access.

FLOYD HULL STADIUM
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: FLOYD HULL STADIUM

LOCATION: 2800 Southwest 8 Avenue

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Larry Ewald, Suzanne Broucek, Bob Stried

FACILITY CONTACT/PHONE: Floyd Hull 566-4395

A.D.A. CONCERNS: Field #1: Restrooms are not accessible and do not meet requirements.

Concession stand counter too high.

Has a designated wheelchair seating area without overhead protection.

Stadium pressboxes are not accessible.

Dugouts have small steps to prohibit wheelchairs. They do, however, have space for wheelchairs.

Metal tie rods on south press box lower level is a protrusion for blind person.

Northside gate with ticket booth has no accessibility, and booth lacks proper counter height.

Sidewalk is needed around entire stadium complex to improve accessibility. Steps to Grandstand have no markings for visually impaired.

Field #2: Back entrance to visitors dugout too narrow. Dugouts have room for wheelchair, but they have a step up.

No designated disabled seating.

Steps to grandstand have no markings for visually impaired.

Restrooms are not accessible and do not meet requirements.

Field #3: Sidewalks needed to field for accessibility. Small lip on dugouts prevents wheelchair access.

Concession stand has no access and counter too high.

Field #4: (Girls) No access to bleachers or field. Room is available in dugout for wheelchair.

Ramped entrance on west side too steep (6").

Steps need to be marked for visually impaired.

Playground: No access to playground is available. None of the playground equipment is accessible.

Parking: We counted 100 spaces in the stadium/Morton Activity Center complex. Six (6) spaces are designated for disabled. This exceeds the requirements. The spaces do need to be relined to meet requirements. They may wish to consider moving some of the disabled spaces to the east side of Field #1 nearer to the disabled entrance and designated seating areas.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION

FACILITY: FORT LAUDERDALE CONSERVATION CORP TRAINING CENTER

LOCATION: Lincoln Park

DATE OF INSPECTION: March 26, 1993

INSPECTOR(S): Bob Stried, Suzanne Broucek, Larry Ewald

FACILITY CONTACT/PHONE: Lucky Jordan

A.D.A. CONCERNS: Parking lot has one designated disabled space. It needs to be relined.

There are no curb cuts at sidewalk.

Office entry door threshold is too high. It also has a gripper door handle.

Counter entrance to office area is too narrow. (Remove old gate form.)

Office restrooms do not meet any requirements.

All doors in the office area are too narrow (30").

Water fountain is recessed into wall which doesn't allow enough space.

Thermostat is too high.

Public restrooms (outside) do not meet any requirements.

Classroom entrance: threshold is too high.

Classroom doors are too narrow, and they have gripper handles.

Pay phones in hall are too high.

Fan switches are too high.

Study stations too low in classroom and library.

Library doors are too narrow.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: FORT LAUDERDALE HIGH - TENNIS & POOL

LOCATION: 1600 Northeast 4 Avenue

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Mike Fay, Jim Kern, Larry Ewald, Bob Stried,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated disabled parking.

Tennis court access is on south side. That area is in disrepair due to the removal of portable classrooms. This area needs to be upgraded.

Pool entrance ramp is too steep.

Water fountain does not meet requirements.

Restrooms and showers do not meet requirements.

No access provided to pool.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: GEORGE ENGLISH PARK

LOCATION: 1101 Bayview Drive

DATE OF INSPECTION: December 4, 1992 and
February 17, 1993 (Docks & Parking)

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek, Susan Retz,
Mike Fay

FACILITY CONTACT/PHONE: Carl Sallade - 396-3620

A.D.A. CONCERNS: Parking lot has 50 spaces with no disabled spaces. Two (2) are needed. Curb cuts would also be needed.

Recreation office is not accessible (steps).

East tennis courts are accessible.

Hardware on gate needs to be adjusted lower.

Bleachers by east court are not accessible.

Old bench should be removed. It blocks bleachers and is not safe.

Water fountain by tennis courts is not accessible.

Steps to dock need to be marked and handrails are not long enough.

Dock has no handrails.

Paddle boats are not accessible.

No access to tennis practice wall.

Ballfield is not accessible.

Tetherball is not accessible.

Basketball court is not accessible.

Playground is not accessible and no equipment meets requirements,

Pay phones are too high, and the surface in front of the phones is not flat.

Electrical disconnects behind building protrude onto sidewalk.

Signage on tennis courts is flat and too high.

Vending machines dollar bill slot is too high.

Accessible water fountain is blocked by steps (by office).

North outside restrooms do not meet any requirements.

Pavilion does not have an accessible picnic table.

Building entrance by pavilion has no level landing.

Door handle is a gripper.

Signage on door is needed to show accessible entrance.

Assembly room:

Door pressure too high (10 lbs). Closes too fast.

Tables are too low and offer no extension.

Window blind controls are too high.

Water fountain is blocked by junk.

All interior doors pressure is too high.

Women's restroom/locker room:

Entrance door too much pressure and has no signage.

Toilet is too high (20").

Grab bar may not support 250 lbs.

Stall does not have the required floor space.

Sink faucets are borderline.

Soap dispensers need a lot of pressure to operate.

Men's room same as ladies.

Docks & Parking:

Docks are not accessible due to width at entrance.

Railings required for visually impaired.

No designated disabled parking.

Pay phones are not accessible due to parking stops in front of them.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: GREEN FIELD

LOCATION: Fort Lauderdale - Northeast

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space with accessible walkway, two benches and one trash can.

Small tree needs to be trimmed because of blocking sidewalk at curve.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: GUTHRIE BLAKE

LOCATION: Southwest 28 Avenue & Southwest 1 Street

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No access into park, sidewalks are needed.

Playground has no accessible play equipment. It is also surrounded by sand.

Park also has two (2) picnic tables, two (2) benches and two (2) grills which are not accessible.

There is no designated parking for anyone.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HARBORDALE

LOCATION: 900 Southeast 15 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park has been taken over by portable classrooms for Harbordale Elementary School.

The playground equipment left is surrounded by sand and is not accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

26.

FACILITY: HECTOR PARK

LOCATION: Southeast 11 Street & Ponce De Leon

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space with three (3) benches and trash cans. There are no sidewalks, no parking and no services offered.

Curb cuts and sidewalks would be needed for full access.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK

LOCATION: Northeast 12 Avenue & G.H. Martin Drive

DATE OF INSPECTION: March 1, 1993

INSPECTOR(S): Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS:

Parking: The gymnasium parking lot has 110 spaces to the north and 33 in front of the facility. None are available for disabled. One is needed.

Social Center has 39 spaces of which three (3) are disabled.

Parking across from the Tennis Center has 35 spaces. None are designated for disabled.

Parking by the train and pavilions has 78 spaces with no disabled spaces available. Four (4) would be needed.

Field #1: Press box is not accessible.

No sidewalk to bleacher areas.

Dugouts are not wide enough for access.

Batting cage is not accessible.

Concession stand counter is too high and not accessible.

Field #2: Dugout on first base is not accessible.

Concession stand is not accessible and counter is too high.

Restrooms adjacent to field do not meet any requirements.

Pay phone is too high.

Field needs a crosswalk and paved path to parking lot across street.

Curb cuts would also be needed.

Field #4: Dugouts are not accessible.

No walkway to the field.

Batting cage is not accessible.

Drinking fountain protrudes on sidewalk and does not provide enough flat space in front of it.

Concession stand counter is too high.

Pay phone has no sidewalk.

Press box is not accessible.

Restrooms do not meet any requirements.

Fields #5 & #6: These fields are not accessible.

Jogging trail signage does not meet requirements for visually impaired.

T-ball fields are not accessible.

Horseshoe pits are not accessible.

Basketball courts are not accessible.

Library field (soccer) has no access.

Plane signage too high and no sidewalk to get there.

Memorial Drive entrance sign is too high and not readable.

No curb cuts on Sunrise Boulevard and Memorial Drive entrance.

Playground is not accessible and no equipment meets requirements. Benches have no access. Curb cuts are also needed.

Pavilion #1: No picnic tables provide wheelchair access. Tables are permanent and very close together.

Grills need to be straightened towards concrete for access.

Signage flat and too high.

Pavilion #2: No sidewalk is available.

No picnic tables provide wheelchair access. Tables are permanent and very close together.

This park is in need of a sidewalk system throughout the park. The sidewalk should start at the U.S.1 entrance and connect all the facilities and buildings within the park. The sidewalks should connect all other entrances into the park.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK ACTIVITY CENTER

LOCATION: Holiday Park/Northeast

DATE OF INSPECTION: March 2, 1993

INSPECTOR(S): Suzanne Broucek, Larry Ewald, Jim Kern, Bob Stried

FACILITY CONTACT/PHONE: Terri Messler - 761-5420

A.D.A. CONCERNS: Designated disabled parking meets requirements, but it needs to be relined. Small trees on sidewalk by disabled parking need to be trimmed for better access.

Picnic table on grounds does not meet requirements.

All interior and exterior doors need adjusting to the correct pressure.

Entrance has a lip that needs to be filled in.

Customer counter is too high.

Fire extinguisher is too high.

Water fountains are mounted too low, and do not spray high enough.

No ramp to dance floor.

Men's restroom inner door too heavy and has no signage.

Urinal is too high. Disabled toilet area is not wide enough and lacks adequate floor space.

Towel and soap dispensers are too high.

Men's locker room shower meets code except for soap dispenser which is too high. It also needs a hand held shower hose at least 60".

Ladies' restroom and locker room have the exact same problems, except for the urinal.

Fire alarm has no visual alarm.

Dollar bill slot on vending machine is too high.

No signage for the visually impaired. Most signage is too high and flat.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK COMMUNITY CENTER

LOCATION: Holiday Park/Northeast

DATE OF INSPECTION: March 2, 1993

INSPECTOR(S): Suzanne Broucek, Larry Ewald, Jim Kern, Bob Stried

FACILITY CONTACT/PHONE: Bob Stones - 761-5419

A.D.A. CONCERNS: Designated disabled parking needs relining and new signage.

Entrance ramps are too steep and do not provide flat area for opening doors.

Door bell is too high.

Stage and office on stage are not accessible.

Restrooms are somewhat accessible. The required floor space is not available. Mirrors, towel and soap dispensers need to be lowered.

Exterior entrance ramp to pottery room is too steep. It also has no flat surface at top.

Door knobs need to be replaced.

Fire alarm has no visual alarm.

Fire extinguisher is too high and is a protrusion for visually impaired.

Air conditioning controls are too high.

Office service counter is too high.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK GYM

LOCATION: Holiday Park/Northeast

DATE OF INSPECTION: March 2, 1993

INSPECTOR(S): Suzanne Broucek, Larry Ewald, Bob Stried, Jim Kern

FACILITY CONTACT/PHONE: Linda Probert - 761-5391

A.D.A. CONCERNS: The gym area has 33 parking spaces on the front and 100 spaces on the north side. None of the spaces are designated for disabled. Eight (8) would be required. This parking area also services fields 5-6, the jogging track and the racquetball area.

All doors need to be adjusted to the proper pressure.

Restrooms do not meet any requirements.

Locker rooms do not meet any requirements.

Stage is inaccessible.

Water fountains do not meet requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK SOCIAL CENTER

LOCATION: Holiday Park

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald, Mike Fay,
Jim Kern

FACILITY CONTACT/PHONE: Judy Thom - 761-5383

A.D.A. CONCERNS: Lobby door pressure needs to be adjusted to 8 lbs. pressure. All other interior and exit doors need to be adjusted to proper pressure.

Restroom signage is too high and flat.

Card tables are too low.

Banquet tables are too low.

Air conditioning controls are too high.

Kitchen fire extinguisher is too high.

Hearing impaired device may be considered for this facility.

Outside signage needs to be upgraded for visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HOLIDAY PARK SPECIAL EVENTS BUILDING

LOCATION: Holiday Park/Northeast

DATE OF INSPECTION: March 2, 1993

INSPECTOR(S): Suzanne Broucek, Larry Ewald, Jim Kern, Bob Stried

FACILITY CONTACT/PHONE: Greg Martin - 761-5976

A.D.A. CONCERNS: Offices share parking with playground next to it. There are 78 spaces in lot with no designated disabled spaces. Four spaces would be required.

Disabled parking could be placed on west side. With signage and back door bell, accessibility to and into the building could be possible.

Front entrance has steps and offers no accessibility. The back door provides accessibility, but only to the conference room level. There is another step up to the front offices and restrooms.

Restrooms do not meet any requirements.

Fire alarm does not meet requirements for hearing impaired.

Conference room table is too low (28").

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: HORTT

LOCATION: 1700 Southwest 14 Court

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Mike Fay, Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking for anyone.

No access in park, sidewalks are needed.

Playground has no accessible play equipment. It is also surrounded by sand.

A par course exists in the park. This course has no trail which makes it not accessible. The station signage does not meet the requirements for visually impaired.

Basketball court has no access.

Softball field has no access.

Bleachers have no access.

One (1) bench and two (2) garbage cans with no access.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: IMPERIAL POINT

LOCATION: 5900 North Federal Highway

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Bob Stried, Larry Ewald
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Open green space in front of Imperial Point. No parking
or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: J. J. VERA'S PARK

LOCATION: Southwest 11 Place & 15 Avenue

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open "green" space.

No parking or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION

FACILITY: LANDINGS

LOCATION: 5400 North Federal Highway

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Larry Ewald, Bob Stried,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Open green space in front of the Landings. No parking
or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: LAUDERDALE MANORS PARK

LOCATION: 1341 Chateau Park Drive

DATE OF INSPECTION: January 14, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Mike Kay, Jim Kern, Suzanne Broucek

FACILITY CONTACT/PHONE: Kay Livingston - 761-5403

A.D.A. CONCERNS: Parking lot has 20 spaces with no lining and no designated disabled parking. Lot needs one.

Signage too high and lacks contrast.

Playground has access, but not to the equipment. Equipment has no accessible apparatus.

No access available to hard courts, basketball and racquetball.

No access to baseball field, and no wheelchair seating available in dugout.

Pool Area: Restrooms are not accessible and do not meet any requirements.

Pool office is not accessible.

Pool water is not accessible, needs a lift.

Shaded area has no wheelchair space.

Pool rules sign needs to be improved for visually impaired.

Pool water fountain is not accessible.

Pool showers do not meet requirements, no seats, no stalls, wrong handles, etc.

Community Center: Water fountain in children's room is not accessible.

Air conditioning controls too high.

Fire Extinguisher is too high.

Kitchen door pressure needs to be adjusted to 5 lbs.

Kitchen dispensers are too high.

Office doors are too narrow - 30" & 31".

Women's Restroom: Entrance door hardware does not meet requirements.
Door pressure too high.

Mirror is too high.

No grab bars.

Stall door not wide enough.

Men's Restroom: Door pressure too high (14 lbs).

No stall door on disabled toilet.

Grab bar needs to be reattached to wall.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: LAUDERDALE PARK

LOCATION: Southwest 4 Avenue & 22 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space with an accessible sidewalk through the middle of the park. No parking or services are available. Curb cuts are needed on sidewalk on 4th Avenue.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: LAUDERDALE VILLAS ENTRANCE

LOCATION: Northwest 14 Street & Northwest 9 Avenue

DATE OF INSPECTION: January 14, 1993

INSPECTOR(S): Susan Retz, Jim Kern, Bob Stried, Mike Fay, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Open green space - not meant to be accessible for public use.

Sidewalk - no curb cuts either side (sidewalk adjacent to NW 9 Avenue).

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: LINCOLN PARK

LOCATION: 600 Northwest 19 Avenue

DATE OF INSPECTION: January 28, 1993

INSPECTOR(S): Bob Stried, Susan Retz, Mike Fay, Suzanne Broucek,
Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Park offers a large green space with sidewalk circling park.

No access to basketball court.

Play equipment is not accessible and is surrounded by sand.

Benches around playground are loose from the base.

Sidewalk edges and dropoffs by planted areas need to be filled in.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: MAJ. WILLIAM LAUDERDALE PARK

LOCATION: Southwest 11 Avenue & 4 Street

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space.

No designated parking spaces are available for anyone.

Two (2) trash cans and a memorial plaque are not accessible. Sidewalks would be needed.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: MERLE FOGG/IDLEWYLD

LOCATION: East Las Olas & Idlewyld Drive

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Bob Stried, Larry Ewald,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No disabled parking available.

No access to dock, benches or table, garbage can (off sidewalk).

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: MILLS POND PARK

LOCATION: 2201 Northwest 9 Avenue

DATE OF INSPECTION: January 21, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Mike Fay, Susan Retz

FACILITY CONTACT/PHONE: Jack Boland - 761-5979

A.D.A. CONCERNS: Gatehouse has no designated parking. Door threshold is too high.

Administration building has 49 parking spaces with 3 disabled spaces.

Entrance doors' thresholds are too high and the door pressure is too high.

Restrooms do not meet requirements because of lack of floor space and no sink in stall.

Drinking fountain is not accessible.

Exterior drinking fountain is not accessible.

West counter is too high.

Kitchen counter is too high.

Thresholds for all other doors are too high.

Air conditioning controls are too high.

Alarm control pad is too high.

Softball office trailer:

Handrail on ramp does not meet requirements.

Door pressure is too heavy.

Interior routes are crowded with storage items.

Restroom does not meet all requirements.

Playground is not accessible and has no accessible equipment.

Picnic tables have no access.

Disabled parking by softball fields needs to be relined.

Paved walkways are needed from each disabled parking area to center of fields.

Field restrooms:

Entrance doors need to have pressure adjusted to 8 lbs.

Signage is too high and does not meet requirements.

Soap dispensers are too high.

No soap or towels in men's room.

Concession stand:

Counter is too high.

Disabled table needed on deck.

Pay phones are too high (56").

Dock does not have a firm slip resistant surface.

Dock is not 60" wide.

Small picnic shelters are not accessible.

Nature trail is not accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: MORTON ACTIVITY CENTER

LOCATION: Southwest 28 Street & 8 Avenue

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: Floyd Hull - 566-4395

A.D.A. CONCERNS: All doors, including entrance, must be adjusted to proper opening pressure.

Restrooms do not meet requirements including signage, floor area, sinks, dispensers, door handles, etc.

Water fountains are not accessible.

Stage is not accessible. P.A. equipment is not accessible.

All signage inside building is too high and flat.

There are no visual or sound fire alarms.

Kitchen is crowded and has minimal access. It is all shared with concession stand for girls' field.

Parking information see Floyd Hull Stadium.

Ramp entrance to building is: Ramp One - 3"
Ramp Two - 4 1/2"
Ramp Three - 4 1/2"

Ramps Two and Three do not meet requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: NORTHFORK

LOCATION: 101 Northwest 15 Street

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking is available for anyone.
Basketball court is assessible, the rest of the park is open green space.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: PARKS & RECREATION ADMINISTRATION OFFICE

LOCATION: 301 North Andrews Avenue

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: Tom Tapp, 761-5348

A.D.A. CONCERNS: This facility has a total of 57 parking spaces with 38 non-metered, 18 metered and one (1) disabled space in the far Northeast corner of the lot. A total of three (3) disabled spaces are required, and they should be closer to the facility.

Entrance ramp to front entrance is too steep (4 3/4"). Small ramp in front door is also too steep.

Entrance door needs to be adjusted to 8 lbs. pressure.

Drinking fountain does not meet requirements.

Restroom doors are too narrow. The outside and inside doors are too close together. Signage on doors is flat. The restrooms do not meet any requirements.

Fire Alarm is audio only.

Doorway to copy/mailroom is too narrow.

Back door curb cut is blocked by an assigned parking space.

Front entrance counter too high. Front desk employee would need to provide services at the front of their desk.

Direction sign at entrance could not be hand read due to location in garden.

This office would most likely be the best location for a department TDD phone for parks and rec information.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: POINCIANA PARK

LOCATION: Southeast 4 Avenue & 21 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space around two city water towers. No parking or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: PROVIDENT PARK

LOCATION: 1400 West Sistrunk Boulevard

DATE OF INSPECTION: January 28, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Susan Retz, Suzanne Broucek,
Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Open green space with a sidewalk around park.

No designated parking for anyone.

Permanent tables have no access. They are too low.

Tree cut out areas need fill to avoid tripping.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: RIO VISTA PARK

LOCATION: Rio Vista Boulevard & Southeast 9 Avenue

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald.

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space with two benches and trash cans. No parking is available and a sidewalk to the benches would be needed to make it accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: RIVERSIDE PARK

LOCATION: Southwest 5 Place & 11 Avenue

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated parking for anyone.

There are two sidewalk accessible entrances - Northeast and Northwest corners of park.

Great sidewalk system around park to building and playground. Additional sidewalks are needed to access basketball court and benches.

Tennis court entrance needs additional paving for good access.

Playground equipment has no access and is surrounded by sand.

The small building has a good ramp without handrails.

Drinking fountain is accessible but mounted too high. Stored equipment should be moved for better access to fountain.

The restrooms are very old and do not meet the requirements in any form.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: RIVERWALK

LOCATION: Southeast Second Street

DATE OF INSPECTION: March 16, 1993

INSPECTOR(S): Jim Kern, Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS:

Riverwalk West:

Two disabled parking spaces are available behind post office.

Trees over walkway need to be trimmed when causing a protrusion for visually impaired.

Picnic tables are not accessible.

Riverwalk signage at Historical Society does not meet requirements for visually impaired (flat and encased).

Riverwalk East:

Water taxi landing is not accessible due to steps.

Steps need to be painted for visually impaired.

No curb cuts are available in dock permit zones.

No wheelchair access onto walk off of Southeast First Avenue.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: ROGERS FIELD

LOCATION: 700 Southwest 26 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park has been taken over by portable classrooms for Rogers Middle School.

No services are offered here at the present time.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SISTRUNK EAST ENTRY

LOCATION: 200 West Sistrunk Boulevard

DATE OF INSPECTION: January 28, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Mike Fay, Suzanne Broucek,
Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space with a small stage. It also has a mural wall with a black history theme.

The ramp to the mural on the west end is too steep.

No designated parking for anyone.

Park sign could use more contrast for visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SNYDER PARK

LOCATION: 3299 Southwest 4 Avenue

DATE OF INSPECTION: March 17, 1993

INSPECTOR(S): Jim kern, Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: Ronnie Lakatos - 468-1585

A.D.A. CONCERNS: Park has over 500 parking spaces throughout the park. There presently is one designated disabled space. There are two additional spaces being added to the beach area.

Park has 19 pavilions with only one designated disabled.

Disabled pavilion:

Picnic tables are too low.

No access to grills, and grills do not meet requirements.

Garbage cans are too high.

No access to water spigot.

Electrical outlet is mounted too high.

Disabled parking space needs to be relined.

Water fountain does not meet requirements.

Restrooms near disabled pavilion:

Men's room toilet is too low.

No mirror, towels or soap are available.

Sink is good but not working. Faucet needs to be changed.

Door into stall is too narrow.

Ladies' room has the same problems as the men's room except it has a mirror.

Nature trail needs benches in rest area. Entrances and exits to trails should be resurfaced for better accessibility. Entrance at east end needs to be cleaned off.

Signage is needed for trail.

No access to fishing area.

Beach Area:

Ramp is currently being constructed to provide access to water.

Playground is not accessible and has no accessible play equipment.

No access is available to paddle boat area or dock.

All signage does not meet requirements for visually impaired.

Water fountain does not meet requirements and has no access.

Restrooms in beach area do not meet any requirements.

Ballfield does not have access.

Volleyball does not have access.

Terrace Pavilion:

Playground does not have accessible equipment and is surrounded by sand.

Pay phone in area does not have access.

Horseshoe pits are not accessible.

Pavilion needs a paved walkway from road for access.

Water fountains do not meet requirements, spout is at wrong angle and there is not enough floor space.

Restrooms do not meet requirements.

Kitchen counter is too high.

Serving tables in grill area are too high.

Grills do not meet requirements.

No picnic tables meet requirements.

Office Area:

Main office is inaccessible due to step up.

Inside service counter is too high.

Water fountain does not meet requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SOUTH BEACH PARK

LOCATION: 600 South A1A

DATE OF INSPECTION: March 4, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Mike Fay, Jim Kern,
Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Parking lot has 650 spaces with two (2) designated disabled spaces. The spaces need to be relined. Two (2) disabled spaces do not meet requirements.

The three (3) restroom facilities are not accessible (step) and do not meet any requirements.

Showers are not accessible.

Playground equipment is not accessible (sand) and does not meet requirements.

No access to picnic tables and they do not meet requirements.

No access to grills and they do not meet requirements.

Volleyball courts are not accessible.

No access to ocean. Beach wheelchairs could be used.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: STRANAHAN - POOL

LOCATION: 1800 Southwest 4 Avenue

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Mike Fay, Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Parking lot offers approximately 25 spaces with no designated disabled spaces. The parking lot is also a rough surface.

There is no ramp available to the pool from the public parking area. There is an available ramp on the north end of the pool from the school building.

There is no access to the pool. A lift would be needed.

Water fountain has no access.

Public phone at entrance is mounted in a box that is too high.

There is no access into the locker/restroom area. (High step)

Restrooms and locker rooms were not available for inspection.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: STRANAHAN PARK

LOCATION: Broward Boulevard & Andrews Avenue

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space with excellent walkways.

There is no designated parking. However, eight (8) metered spaces exist on the east side of the park along Southeast First Avenue. There are no disabled spaces designated.

The historical walkway has plaques about the history of Fort Lauderdale. They are not accessible for the visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNLAND GYM

LOCATION: Sunland Park

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Entrance doors need to have door pressure adjusted.

Gym floor is too steep to get up to.

Men's and Women's locker rooms do not meet any requirements.

Men's and Women's restrooms do not meet any requirements.

Stage is not accessible.

Office is not accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNLAND PARK

LOCATION: 1448 West Sunrise Boulevard

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: Lillian Edden - 761-5410

A.D.A. CONCERNS: Main field parking lot has 303 parking spaces with NO designated disabled spaces. Thirteen disabled spaces are required.

Tennis courts are accessible off the east side. Tennis signage is too high and flat.

Racquet ball courts have no access.

The park is in need of sidewalks around the park. This would connect all courts and fields.

Baseball bleacher areas need to provide wheelchair area by sliding bleachers to one side of the concrete slab.

Field #1 needs bottom of cement light pole painted for visually impaired.

Lip at concrete entrance to east dugout needs to be corrected.

Playground & picnic area has no designated disabled parking. No accessible picnic tables, shelters, trash cans or grills are available. Playground is not accessible and equipment does not meet requirements.

Shuffleboard courts are not accessible.

Basketball courts need small paved walkway from sidewalks for accessibility.

Handrails on ramp to pool need to be extended at bottom.

Building parking lots have no disabled parking spaces. They need four (4).

Curb ramp to building does not meet requirements.

Wheelchair access from Sunrise Boulevard is too steep.

Signage at parking is too high, flat and fading.

Outside railing on back of Social Center is very high. Steps need to be marked for visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNLAND POOL

LOCATION: Sunland Park

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzannie Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Signage on walks is faded.

Accessible water fountain is broken.

Ramp to guard office is too steep.

Restroom in guard office is accessible with no signage.

Mirror is too high.

If hot water is available, pipes need to be insulated.

Men's and Women's locker rooms are not accessible and do not meet any requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNLAND RECREATION CENTER

LOCATION: Sunland Park

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: No designated disabled parking.

Restrooms (indoors): Men's room mirror is too high. Signage is too high.
Entrance door lip is too high.

Ladies' room entrance door pressure needs to be adjusted. No signage.

Restrooms (outdoors): Lip at door entrances too high. Signage is too high and no accessible signs.

Rec Center main entrance lip is too high.

Counter is too high.

Vending machine blocks wheelchair access in hallway.

Vending machine is too high.

Air conditioning control is too high.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNLAND SOCIAL CENTER

LOCATION: Sunland Park

DATE OF INSPECTION: February 18, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Disabled parking needs to be added.

Water fountain is blocked by portable steps.

Restrooms do not meet any requirements.

Stage area is not accessible.

Office door is too narrow.

Entrance door thresholds are too high.

Kitchen counters are too high.

No visual fire alarm.

Tables are too low to meet requirements.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SUNSET

LOCATION: 3775 Southwest 16 Street

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS:

Peters Field (west End): Great access to bleachers and one dugout. The other dugout needs a short piece of concrete to complete walk.

Concession stand counter is too high.

Press Box lacks access.

Access into restrooms is available (no steps), but beyond the doors they do not meet any requirements.

Access is available up to the playground. The equipment offers limited access with one piece available for a "transfer". The equipment is surrounded by sand.

Football Field: There is no access to bleacher areas.

Concession stand counter is too high.

Access into restrooms is available (no step), but beyond the doors they do not meet any requirements. No signage on doors.

Softball Field (east): No access to field or bleachers, should be finished like Peters field.

No access to basketball courts.

No access to chin-up bars.

Both the east side and west side of the park have double fence entrances that are not wide enough for access.

Sidewalks around the park connecting all the areas would improve access.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SWEETING PARK

LOCATION: NORTHWEST 23 AVENUE & 4 STREET

DATE OF INSPECTION: January 28, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space with no accessibility.

No designated parking for anyone.

A very old clock exists on the water with no accessibility for anyone.
Should be repaired or removed.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: SWIMMING HALL OF FAME

LOCATION: 501 Seabreeze Boulevard

DATE OF INSPECTION: March 23, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: Stu Marvin - 468-1580

A.D.A. CONCERNS: Parking lot has 100 parking spaces with 5 designated disabled. Car stops should be painted blue. The far east space should also be relined to make better use of curb cut.

Pool Area:

Entrance counter is too high. (Staff comes out of office to serve public).

Beach Patrol office counter is too high.

All administrative offices, press room, swim team offices, upstairs and downstairs are not accessible.

Weight room for swim team is not accessible (step up).

Ladies locker room & restroom:

Shower does not meet requirements. It needs a seat and a hand held shower 5 feet long.

Soap dispenser in restroom is too high.

Entrance door is too heavy.

Ramp into locker room is too steep.

Men's locker room:

Shower does not meet requirements. It needs a seat and a hand held shower 5 feet long.

Ramp into locker room is too steep.

Entrance door is too heavy.

Bleacher area is not accessible.

Wheelchair seating is provided on deck.

All steps in bleacher area need to be painted for visually impaired.

Swimming Hall Of Fame - Page 2.

Exit ramps from bleacher area are seldom used, but they are too steep.

Museum & Pro Shop:

Entrance door threshold is too high (1 3/4").

Exhibits do not meet requirements for the visually impaired.

Computer TV screens are too high for wheelchair viewing.

Restrooms:

Men's room signage is too high.

Sinks are too high.

Mirror, soap and towel dispensers are too high.

Door is too heavy and closes too fast. Door handle is a grip and turn needs to be replaced.

Ladies' room signage is too high.

Door is too heavy.

Sink, mirror, towel and soap dispensers are too high.

Disabled toilets in both restrooms have been modified to meet code. They have a plastic extension under seat that raises the toilet. It doesn't look good and is probably harder to maintain.

Stairs need to be marked for visually impaired.

Museum should provide a tape recorder with tour through exhibits for visually impaired.

Bikes are being locked to handrail entrance, creating protrusions for the visually impaired.

Ramp should be installed at the west end of north walkway towards the Auditorium. (Steps are cracked.)

Art Gallery side entrance ramp is too steep. No signage for bell entrance. Bell is hard to find.

Front entrance door is too heavy and the threshold is too high.

Water fountain does not meet requirements.

Downstair restrooms do not meet requirements in any way.

Swimming Hall of Fame - Page 3.

First floor does not have full access because of steps near conference room and offices.

Auditorium:

Entrance threshold is too high. Door is too heavy.

Pay phone does not meet requirements.

Interior entrance door does not meet requirements.

Restrooms do not meet requirements in any way.

West entrance door is too heavy, and the threshold is too high.

Upstairs offices have restrooms that meet requirements. Offices are not always open during events held downstairs. Elevator is available.

Curb cuts should also be installed at turnaround where sidewalks meet.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: TARPON COVE

LOCATION: Southwest 11 Court

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park is a street end. It offers green space with no designated parking or services available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: TARPON COVE

LOCATION: Southwest 11 Court

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park is a street end. It offers green space with no designated parking or services available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: TARPON RIVER PARK

LOCATION: Southwest 11 Court, West of Andrews

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space. No parking or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: TENNIS CENTER

LOCATION: Holiday Park

DATE OF INSPECTION: March 1, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: Jimmy Evert - 761-5378

A.D.A. CONCERNS: Forty-Two (42) parking spaces require two (2) disabled spaces. Facility presently has one (1) which needs to be relined.

No access to wooden deck entrance area. Wooden deck also has some cracks which a wheelchair wheel could get caught on.

The covered seating areas offer no wheelchair space.

None of the drinking fountains are accessible.

Office service counter is too high.

Vending area is not accessible due to a step.

Ramp to restrooms is too steep.

Showers are not to code.

Restrooms are very close to code; soap, towel dispensers and mirrors are too high.

Restroom doors need to be adjusted to 8 lbs. of pressure.

The A.D.A. inspection committee determined that a wheelchair would damage a clay court. The Tennis Center offers three hard courts which are accessible. However, those three courts lack lighting. This would limit wheelchair playing to daytime.

Thirty-five additional parking spaces are offered across the street from the center, of which none are designated for disabled parking.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: TOWNSEND PARK

LOCATION: Southwest 14 Avenue & Argyle Drive

DATE OF INSPECTION: March 11, 1993

INSPECTOR(S): Larry Ewald, Bob Stried, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This park offers open green space.

There are 4-5 unlined, unpaved parallel parking spaces, none designated for disabled.

There is no park signage.

There are no sidewalks and no access into park.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: VICTORIA PARK

LOCATION: East Broward Boulevard & Victoria Park

DATE OF INSPECTION: February 17, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Open green space by a canal.

No access is available to bench and seawall. Sidewalk is needed.

Some unpaved parallel parking is available, but none is designated disabled parking.

Sidewalk on north end of park is in need of repair.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: VIRGINIA YOUNG PARK

LOCATION: 900 Southeast 10 Street

DATE OF INSPECTION: March 8, 1993

INSPECTOR(S): Suzanne Broucek, Bob Stried, Larry Ewald

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small playground park has no available parking.
Playground equipment and surrounding benches are not accessible.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: VISTA PARK

LOCATION: 2800 North Atlantic Boulevard

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Bob Stried, Larry Ewald
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: Vista Park offers parking and access to the beach. There is one disabled parking space, without the required curb cut, that needs to be properly lined.

Walkway also needs curb cuts for better access.

Shower is not accessible.

There is no access to the beach or benches.

Steps to beach should be painted for visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WALKER PARK

LOCATION: 1001 Northwest 4 Street

DATE OF INSPECTION: January 28, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Mike Fay, Larry Ewald,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: There is no designated parking for anyone.

This park offers a large green space with sidewalks surrounding it.

The sidewalk has some major dropoffs due to missing school playground.

No access to basketball courts.

No access to tennis courts. The tennis courts also have a broken tennis pole that needs to be removed.

No access to the current restroom facilities. These are scheduled for demolition.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WAR MEMORIAL AUDITORIUM

LOCATION: Holiday Park/Northeast

DATE OF INSPECTION: March 2, 1993

INSPECTOR(S): Bob Stried, Larry Ewald, Jim Kern, Suzanne Broucek

FACILITY CONTACT/PHONE: Bob Stried - 761-5380

A.D.A. CONCERNS: Parking lot offers ten disabled spaces with pavement. For large crowds, additional spaces are put on hold for disabled.

Entrance signage needed. Crosswalk would also be a good idea.

Pay phones are 1/2" too high.

Front door closing could be slower.

Box office window is too high. Alternate service is offered.

Water fountains in lobby need to be adjusted.

Ladies' restroom needs outside signage. It also lacks the required floor space.

Stage area is presently not accessible. A wheelchair lift is on order.

Auditorium lacks listening devices for the hearing impaired.

Backstage restrooms and showers are not accessible.

Dressing room sink pipes should be insulated.

Stage water fountain is not accessible.

Signage at inside entrance is too high.

Fire extinguisher is too high, and it protrudes into hallway.

Auditorium offers no services for the visually impaired.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WARFIELD PARK

LOCATION: 1000 North Andrews Avenue

DATE OF INSPECTION: January 7, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Jim Kern, Mike Fay, Suzanne Broucek

FACILITY CONTACT/PHONE: Anne Davis - 761-5417

A.D.A. CONCERNS: Parking lot is in need of one disabled parking space.

Restrooms are not accessible and do not meet requirements in any form.

Drinking fountain is not accessible.

Fire extinguisher is not accessible.

The back room area is not accessible due to step up.

Courtyard is rough.

Playground offers no accessibility and no equipment meets requirements.

Softball field has no access.

This small facility would be a good example of a facility that should be demolished and rebuilt. It would be better and cheaper than trying to meet A.D.A. requirements with existing structure.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WESTWOOD HEIGHTS

LOCATION: Southwest 7 Street & 29 Avenue

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: The playground has been taken over by portable classrooms for Westwood Heights Elementary School.

There is no designated parking for anyone.

The three (3) baseball fields north of the school are all the same. They offer no access because of a double fence entrance. Dugout areas are small and offer little.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WESTWOOD TRIANGLE

LOCATION: East of Westwood Heights

DATE OF INSPECTION: March 10, 1993

INSPECTOR(S): Bob Stried, Mike Fay, Larry Ewald, Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space. No parking or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION DEPARTMENT

FACILITY: WILLINGHAM

LOCATION: Northeast 21 Street and North Atlantic

DATE OF INSPECTION: February 24, 1993

INSPECTOR(S): Jim Kern, Mike Fay, Bob Stried, Larry Ewald,
Suzanne Broucek

FACILITY CONTACT/PHONE: None

A.D.A. CONCERNS: This small park offers open green space with sidewalk on west side. No parking or services are available.

A.D.A. INSPECTION REPORT
FORT LAUDERDALE PARKS & RECREATION

FACILITY: YANKEE STADIUM

LOCATION: 5301 Northwest 12 Avenue

DATE OF INSPECTION: February 4, 1993

INSPECTOR(S): Susan Retz, Bob Stried, Mike Fay, Suzanne Broucek,
Jim Kern

FACILITY CONTACT/PHONE: Vince Gizzi - 938-4980

A.D.A. CONCERNS: The stadium provides 30 disabled spaces which do not meet code. The spaces are improperly lined as they do not provide access aisles. Two signs are also missing. Signs that are on site are too low. The spaces could also be moved east to provide better access to the main entrance.

Entrance needs to provide better signage noting the disabled entrance. Ticket counters are too high.

Ramps to the main seating area are too steep.

Stadium girders and office air conditioners protrude into pathway which could create problems for the visually impaired.

First aid room threshold is too high.

Main concession stand counter is too high.

Concession threshold is too high.

Door pressure needs to be adjusted.

Pay phones are too high - 55".

Restrooms: Main grandstand restrooms do not meet requirements. Some of the problems include threshold too tall, stall doors too narrow, lack of clear floor space, toilet too low, grab bars not level, sinks too low and the mirrors too high.

Restrooms west side bleacher area do not meet any requirements.

Restrooms east side bleacher area do not meet any requirements.

Accessible restrooms are available in the Yankee offices and Hospitality Room.

Yankee Stadium - Page 2

Concession stand east side:

Counter is too high.

Electrical main protrudes too far into pathway.

Concession stand west side:

Counter too high

Press Box is not accessible.

West side disabled bleacher seating handrails are too low and have no extensions to flat area.

Bleacher ticket booth counters are too high.

Stadium seating offers 17 wheelchair seats. The 12 behind home plate have seats available for family members.

The auxiliary area which provides five (5) seats is not covered.

Steps throughout the stadium should be painted or stripped for the visually impaired.

There are no services provided for the hearing impaired.

There are no accessible drinking fountains.

Hospitality Room:

Restrooms need minor adjustments:

Door pressure needs to be adjusted.

Exposed hot water pipes need to be insulated.

Mirrors are too high.

Men's room sink is too high.

Kitchen threshold is too high.

Yankee & Visitors Clubhouses:

Restrooms are not accessible.

Showers are not accessible.

Drinking fountains are not accessible.

Threshold is too high.